

1/7




FIG. 1

2/7




FIG. 2

3/7





FIG. 3

4/7




T1 : BLOW MODE TIME

T2 : FUSE LATCH RESET MODE TIME

T3 : POINTER ADVANCE MODE TIME

FIG. 4A

5/7




T1 : BLOW MODE TIME

T2 : FUSE LATCH RESET MODE TIME

T3 : POINTER ADVANCE MODE TIME

FIG. 4B

6/7



7/7




FIG. 6